

## City of Milpitas Building and Safety Department

Mailing Address: 455 East Calaveras Boulevard, Milpitas, California 95035-5479 – Tel. 408.586.3240, Fax 408.586.3285 <a href="https://www.ci.milpitas.ca.gov">www.ci.milpitas.ca.gov</a>

Policy:	BDP-BLG07	
Effective Date:	08/19/1992	
Proposed by:	KI	
Last Reviewed/ Revised:	3/24/2014	
Reviewed/ Revised by:	LS/BYC/OC	
Approved By:	Keyvan Irannejad P.E.	

## SPECIAL INSPECTION REQUIREMENTS FOR PRE-CAST WALL COLUMN FABRICATION

Chief Building Official

	COLUMNS 6 FEET	COLUMNS OVER 6
WALL HEIGHT:	HIGH OR LESS	FEET HIGH
Reinforcing Placement		X
Concrete Placement		X
Cast Sample		X
Pick-up Sample		X
Compression Tests		X
Welding	X	X

## **NOTE:**

- 1) Walls over 6 feet in height require special inspection for column fabrication.
- 2) Prior to erecting the panels, submit special inspection report to the City of Milpitas Building and Safety Department.